Division of Health Care Facilities							
STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIPLE CONSTRUCTION		(X3) DATE SURVEY COMPLETED			
AND PLAN OF CORRECTION IDENTIFICATION NUM		······································	A. BUILDING: 01 - MAIN BUILDING 0102		\		
TN2602			B. WING		03/04/2013		
			DRESS, CITY, STATE, ZIP CODE				
1360 BYPASS ROAD							
GOLDEN LIVINGCENTER - MOUNTAIN VIEW WINCHESTER, TN 37398							
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	IULD BE COMPLETE	
N 848 SS=D	(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) 1848 1200-8-608 (18) Building Standards (18) It shall be demonstrated through the submission of plans and specifications that in each nursing home a negative air pressure shall be maintained in the solled utility area, toilet room, janitor's closet, dishwashing and other such soiled spaces, and a positive air pressure shall be maintained in all clean areas including, but not limited to, clean linen rooms and clean utility rooms. This Rule is not met as evidenced by: Based on observation and testing, it was determined the facility failed to maintain negative air pressure in the soiled laundry area and positive air pressure in the clean laundry area. The finding included: Observation and testing of the laundry facility on 3/4/13 at 7:42 AM, revealed negative air pressure in the clean side of the laundry facility and positive air pressure in the dirty side of the laundry facility. This finding was verified by the maintenance director and acknowledged by the administrator during the exit conference on 3/4/13.			N 848	1. On 3/04/13, the Maintenance Director of duct tape covering the air supply vent be soiled laundry room providing positive clean side and negative in the soiled side. 2. All residents within the facility have the tobe affected. 3. a)On 3/05/13, the Maintenance Director laundry staff regarding the requirement systems obstruction free. b) Weekly random audits will be conducted by the Executive Director, Maintenance In Designee to ensure continued compliance. 4. Random audits will be conducted by the Executive Director, Maintenance Director Designee with findings reported month Committee until resolved.	removed the located in the ve air pressure in side. the potential tor re-educated ent to keep vent ducted by Director and/or iance.	
Division of Health Care Facilities (X6) DATE							
LABORATOR	LABORATORY DIRECTOR'S OR PROVIDER'S SUPPLIER REPRESENTATIVE'S SIGNATURE THE DIRECTOR 3/2013						
STATE FORM				5599	Y6QC21	If continuation sheet 1 of	